TECHNICAL DATA SHEET

Sparco Woodshelter Series



Sparco Woodshelter Sanding Sealer



Packing Size

0.91,3.64 Litres

Handling

Handle with care. stir well before use

Storage

The product must be stored in accordance with national regulations. Storage conditions are to keep the containers in a dry, cool, well ventilated space and away from source of heat and ignition. Containers must be kept tightly closed.

Health and Safety

Please observe the precautionary notices displayed on the container. Use under well ventilated conditions. Do not breathe or inhale mist. Avoid skin contact. Spillage on the skin should immediately be removed with suitable cleanser, soap and water. Eyes should be well flushed with water and medical attention sought immediately. For detailed information on the health and safety hazards and precautions for use of this product, we refer to the Material Safety Data Sheet.

Typical Paint System

Sparco Woodshelter Sanding Sealer 2-3 Coats Sparco Woodshelter Top Coat (any) 2-3 Coats

Product Description

Sparco wood shelter sanding sealer is a fast drying sealer with excellent sealing properties. It is specially formulated to fill pores and imperfections of wood. It has excellent durability, toughness, flow and leveling properties.

Recommended use

Sparco wood shelter sanding sealer is a semi gloss high build sealer which is used to seal the pores of wood.

Film thickness and spreading rate

 $\begin{array}{ll} \text{Dry film thickness} & 20\text{-}25~\mu \\ \text{Wet film thickness} & 45\text{-}60~\mu \end{array}$

Theoretical Spreading Rate 11-13 m²/litre/coat

Physical properties

Color water white/pale yellow

 $\begin{array}{lll} \mbox{Finish} & \mbox{Semi gloss} \\ \mbox{Volume solids} & \mbox{40 \pm 5} \\ \mbox{Flash Point} & \mbox{20 °C} \\ \mbox{Specific Gravity} & \mbox{1.10 - 1.20} \\ \end{array}$

Surface Preparation

The substrate must be sound, clean, dry, free from dust, oil and grease etc. All traces of release agents must be removed.

Application methods





Cloth Pa

Drying Time

Temperature	Touch Dry	Recoating Interval	Hard Dry
23 °C	30 min	3 Hours	4 Hours
30 °C	25 min	2 Hours	3 Hours
38 °C	20 min	1 hours	2 Hours

Application Data

System	Single component System	
Thinner	Sparco Woodshelter Thinner	